





Mailing Address:
PO Box 1674
Warsaw, IN 46581-1674

Phone: 844-SEYMOUR
FAX: 574-267-8508
www.seymourmidwest.com

Shipping Address:
2666 S Country Club Rd
Warsaw, IN 46580



Flexible Blade Smoother **Assembly Instructions**

Tools Needed for Assembly:

- 7/16" wrench (two)

Parts Shipped with Unit:

- Head/Blade Assembly
- Threaded handle adapter or aluminum handle (not pictured)
- Gusset brace (set of 2) – one gusset is labeled if unit comes with threaded handle adapter
- Bolt bag for braces

Gusset Brace Instructions:



1. Slide slotted handle or threaded handle adapter over the center hole on the aluminum frame.
2. Position labeled gusset on bottom of adapter, as shown, and the other gusset on top of the adapter. If unit comes with handle, gussets are interchangeable.
3. Insert the two longest bolts through the top gusset, the handle/adapter and the bottom gusset. Insert the two shorter bolts through the two remaining holes on the frame.
4. Tighten all nuts, being careful not to over-tighten. Over-tightening hardware may result in crushing the handle, thereby compromising its strength.

If blade is ever to be replaced, use 3/8" wrench and Phillips screwdriver. Call our toll-free phone number for assistance if needed.

FULL WARRANTY

All Seymour Midwest products carry a full warranty against manufacturer defects in quality and workmanship. Products which have been abused or worn out from normal use are excluded from this warranty. We reserve the right to replace or issue credit on an individual basis.

REPLACEMENT PARTS LIST

See Reverse Side

PK90327
01/21/15

FLEXIBLE SMOOTHER REPLACEMENT PARTS

SP50030	Flexible steel blade – 24”
SP10045	Head – 24” - aluminum
SA20172	Handle – 66” aluminum powder-coated w/ vinyl grip
SP20025	Threaded handle adapter
SA30009	Braces – gusset (set of 2)
SA60023	Bolt bag: 4 bolts, 4 loc nuts (for handle attachment)
RM60101	Bolt – 1/2”x10 – 24 – Phillips head (requires 6)
RM60102	Loc Nut 10x24 – nylon insert (requires 6)